

FIG. 1

TOP SHEET

ON	OFF	ON	OFF	ON	OFF
----	-----	----	-----	----	-----

Q STATUS

VREF1

(FIRST SWITCH RESISTOR)

I<sub>PK1</sub>

VREF2

(SECOND SWITCH RESISTOR)

I<sub>SEC</sub>


V(V<sub>SW</sub>)


V<sub>IN</sub>

V(G<sub>REF</sub>)

B<sub>PW</sub>

FIG. 2



[illegible]
$$F = 6.4$$

60




FIG. 5




FIG. 6




FIG. 7




FIG. 8



**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

### **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☒ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**